DMV Lane Technician Observation Report

| DMV Technician: Questrocaro | Position Tor 2 | | | | | |
|--|---|---|-----|----|-----|--|
| Station: N/ew (25%) Date: (2-30-13 Time: 11:46 | | | | | | |
| Vehicle Make: Chu | Model CAMBIY Year 2002 Type: GAS Registration Number: 804947 | | | | | |
| GVWR: Fuel Type: | WR: Fuel Type: 6 A 5 Registration Number: 809997 | | | | | |
| Auditor: Councale | Auditor: Covert/Overt (Circle One) | | | | | |
| | | | | | | |
| | | | YES | NO | N/A | |
| 1. Did technician check vehicle paper work and verify VIN number? | | - | | | | |
| 2. Was Emissions testing required? | | 1 | | | | |
| a) Was Emissions testing performed using OBD? | | | | | | |
| b) Was Emissions testing performed using Analyzer Probe? | | | | | | |
| c) Was Emissions testing performed using Paddle(s)? | | | | | | |
| d) Was Emissions testing performed using Clip? | | | | | | |
| 3. Was Catalytic Converter inspection required? | | | | | - | |
| a) Was Catalytic Converter inspection performed? | | | | | | |
| 4. Was Fuel Tank pressure testing required? | | | | 1 | | |
| a) Was Fuel Tank pressure testing performed? | | | | | | |
| 5. Was Fuel Cap pressure testing required? | | | | | - | |
| a) Was Fuel Cap pressure testing performed? | | | | | | |
| | | | | | | |
| 6. Is this test a Re-check from a prio | r failure? | | | 1 | | |
| a) Which re-check test is being performed? 1 2 3 (circle one) | | | | | | |
| b) If this is re-check #3, was repair paperwork verified for waiver? | | | | | | |
| | | | | | | |
| Sussex County Only | | | | | | |
| 7. Was Curb Idle testing required? | | | | | | |
| a) Was Curb Idle testing performed | d? | | | | | |
| | | | | | | |
| Comment: | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

DMV Lane Technician Observation Report

| DMV Technician: Lyeras Miguel Position: For 2 | | | | | | |
|--|-----|----|-----|--|--|--|
| Station: New Costny Date! 12-30-13 Time: 11:42 | | | | | | |
| Vehicle Make: Plear 1993 | | | | | | |
| GVWR: Fuel Type: 645 Registration Number: 190 45/64 | | | | | | |
| Auditor: Covert/Overt (Circle One) | | | | | | |
| | | | | | | |
| | YES | NO | N/A | | | |
| 1. Did technician check vehicle paper work and verify VIN number? | 6 | | | | | |
| 2. Was Emissions testing required? | 1 | | | | | |
| a) Was Emissions testing performed using OBD? | - | | | | | |
| b) Was Emissions testing performed using Analyzer Probe? | 4 | | | | | |
| c) Was Emissions testing performed using Paddle(s)? | /_ | | | | | |
| d) Was Emissions testing performed using Clip? | | | | | | |
| 3. Was Catalytic Converter inspection required? | 4 | | | | | |
| a) Was Catalytic Converter inspection performed? | | | | | | |
| 4. Was Fuel Tank pressure testing required? | | | 1 | | | |
| a) Was Fuel Tank pressure testing performed? | | | | | | |
| 5. Was Fuel Cap pressure testing required? | | | 4 | | | |
| a) Was Fuel Cap pressure testing performed? | | | | | | |
| | | | | | | |
| 6. Is this test a Re-check from a prior failure? | | - | | | | |
| a) Which re-check test is being performed? 1 2 3 (circle one) | | | | | | |
| b) If this is re-check #3, was repair paperwork verified for waiver? | | | | | | |
| | | | | | | |
| Sussex County Only | | | | | | |
| 7. Was Curb Idle testing required? | | | | | | |
| a) Was Curb Idle testing performed? | | | | | | |
| | | | | | | |
| Comment: | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |